



Are These Reviews?

The listing appears to show that this seller has 6 reviews and 100% feedback rating.

Seller vs. Buyer

This steel building seller has 6 reviews as a buyer of various eBay items and 0 seller ratings.

Rigid Cee

C channel buildings cannot be engineered for over 30 pounds of snow. Regardless of the photos, this is not to be confused with an I-Beam building.

Building: Codes & Loads

A snow load of 20 is reliable almost nowhere. Missouri has a 30 snow load. Not to mention a 90 wind speed rating wouldn't even work in Kentucky. Raising these after purchase will cost thousands of dollars!

Description

Seller assumes all responsibility for this listing.
Last updated on Jun 28, 2016 09:08:11 PDT View all revisions

Item specifics

Condition: New, unused, unopened, undamaged item in its original packaging (where packaging is applicable). Packaging should be the same as what is found in a retail store, unless the item is handmade or was packaged by the manufacturer in non-retail packaging, such as an unprinted box or plastic bag. See the seller's listing for full details.

Country/Region of Manufacture: United States

Model: Rigid Cee

New 24'x36'x12' 3:12 pitch Do-It-Yourself Steel Building. We are a nationwide supplier of Steel building kits with over 22 years experience in the metal building industry.

This listing is for a base building 24'x36'x12' 3:12 pitch, 20/90 snow wind load, 100% steel building with (2)-9'x8' framed openings and (1)-3070 walkdoor opening, simple eave trim and colored roof. Additional options are 18" overhangs (as seen in picture), 2" 3" 4" or 6" Roof and Wall insulation, Gutters and Downspouts, window framed openings (as seen in picture) wainscote, color roof, lofts (as seen in picture) and lean-to's. Buildings may be custom designed to meet your needs. Typically buildings take 2-3 weeks to deliver from time that we are released to fabricate. Freight is included to most lower 48 states. For questions or pricing please contact us.

Questions and answers about this item

No questions or answers have been posted about this item.

Ask a question

Report item



Included?

✗ Insulation

✗ Doors and Windows

The pictures are deceiving, increased roof pitch, gutters and any other accessories not listed (but shown in pictures) will increase the price. At a minimum you will need to add insulation, (1) 3070 walk door and (2) sectional doors to complete the framed openings. These necessary additions will add approximately \$5-\$6k to the listed price.